



SURVIVAIR®



TECHNICAL BULLETIN

TECHNICAL BULLETIN #127

SUBJECT: Discontinuation of the Use of Never-Seez® on Survivair® Cylinder Valve Threads

DATE: December 19, 2005

PRODUCTS AFFECTED: All Survivair® Cylinder Valves

This Technical Bulletin is to inform all Survivair customers, Technicians, and end users that as of March 2005, Survivair has discontinued the application of Never-Seez® anti-seize compound on all cylinder valve threads of all Survivair products. There is no replacement or substitute lubricant/compound.

Survivair Certified Repair Technicians

Please delete the following information from your Survivair SCBA Cylinder Valve Service Manual.

V. OVERHAUL, A. CYLINDER VALVE, 3. Reassembly, Page 13:

s. Apply a small amount of Never-Seez Lubricant, P/N 820419 (1/4" diameter dab), to the first few threads of the cylinder valve.

NOTE

Not not allow Never-Seez to contact the o-ring or the valve flange surface.

VII RECOMMENDED LUBRICANTS AND CLEANERS, Page 18:

Lubricant/Cleaner	Application	Source
Never-Seez NSBT-16	Valve/cylinder threads	Survivair P/N 820419

F/N: tb127