

T E C H N I C A L B U L L E T I N

#26 October 18, 1985

MANDATORY RETROFIT OF 910150 CAP AND CHAIN ACCESSORY FOR USE ON MARK 2 STYLE SCBA'S.

*******WARNING*******

A polyvinyl tube must be added to the cap and chain assembly (P/N 910150) for use of this accessory on the Mark 2 SCBA unit. Failure to do so may allow the chain to obstruct the movement of the emergency bypass ring. Emergency air may not flow and may cause injury or death by inhalation of toxic fumes. Remove the cap and chain from the regulator until you have completed your retrofit.

SURVIVAIR has modified the 910150 cap and chain assembly for use with the Mark 2 SCBA unit. This modification required the addition of a polyvinyl tube (P/N 996001) to the chain. All future purchases of the cap, chain and tube assembly should be ordered using part number 996004.

Requirements for this retrofit extends only for use on the Mark 2 SCBA's. Retrofit is not required on S-30, Mark I, XL-60's or XL-30 SCBA units.

These tubes may be ordered free of charge (P/N 996001) from your local SURVIVAIR distributor or from SURVIVAIR by calling, toll free, 1 (800) 821-7236. Ask for the cap and chain order desk. Installation instructions are included with each order.